


Figure 3.17-5: Proposed Wildlife Mitigation at the Getty View Trailhead Area



**Attachment
Item 9(1)
SMMC
07-09-2007**